

General Environmental Incident Summary

Incident: 4121 **Date/Time Notice:** 6/7/2016 1745 **DEM Incident No:**
Responsible Party: Sterling Construction Management, LLC
Date Incident: 6/6/2016 **Time Incident:** 1600 **Duration:** 1 minutes
County: Dunn **Twp:** 148 **Rng:** 97 **Sec:** 35 **Qtr:**
Lat: 47.59830 **Long:** -102.99980 **Method:** Navigation quality GPS
Location Description: Bear Creek NGL Pipeline Spread 2 station # 1098+00 (Killdeer nearest town)

Submitted By: Chase Edmiston **Affiliation:**
Address: 100 West Fifth Street
City: Tulsa **State:** OK **Zip:** 74103

Received By:

Contact Person:

10020 HWY 200 East
Dunn Center, ND 58626

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Equipment Failure

Description of Released Contaminant: Drilling Mud

Volume Spilled: 150.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Drilling rig malfunction

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Localized soil impact. No other sensitive resources affected. No visible water body in the area.

Action Taken or Planned:

The rig was shut down when the release was discovered. The drilling mud was contained using silt fence and sandbags. Drill mud was then contained with a vac truck and spread on ROW in an approved designated area.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/9/2016 ***Status:*** No Further Action Requested

Author: Souder, Taylor

Updated Volume:

Notes:

According to the report the release did not contaminate waters of the state. The drilling mud released was not from vertical drilling so no further action needed at this time.